

MANASSAS REGIONAL/HARRY P. DAVIS FIELD (HEF) 4 SW



Sectional Chart: Washington

Runway: Rwy 16L-34R H5700 x 100 (ASPH-GRVD)
Rwy 16R-34L H3702 x 100 (ASPH)

Traffic Pattern: Rwy 16L Left; Rwy 34R Right; Rwy 16R Right; Rwy 34L Left – TPA 1200 (1008) single engine and light twin acft, 1500 (1308) med twin and turboprop acft, 1000 (808) helicopter.

Runway Lights: HIRL (Rwy 16L-34R); MIRL (Rwy 16R-34L)

Rotating Beacon: Yes

Fuel: 100 LL, Jet A

Maintenance: Major AF & PP, FAA 145 Repair Station, AOG Maintenance

Manager: Juan Rivera, 10600 Harry J. Parrish, Manassas, Virginia 20110, (703) 257-8261

Airport Telephone: (703) 361-1882

Airport Operators: Dulles Aviation, Inc., 10501 Observation Road, Manassas, Virginia 20110, (703) 361-2171; APP Jet Center, 9998 Wakeman Drive, Manassas, Virginia 20110, (703) 392-5387.

Hours of Operation: Attended 1130-0330Z±

Remarks: Birds and deer on and invof arpt. Acft

category C III or larger use Rwy 16L-34R and East ramp - ctc arpt manager 703-361-1882. Helicopter ops over residential areas blo 1000' should be avoided. When twr clsd ACTIVATE HIRL Rwy 16L-34R, MALSR Rwy 16L, MIRL Rwy 16R-34L and REIL Rwy 16L, Rwy 34R, Rwy 16R, Rwy 34L – CTAF. U.S. Customs 703-661-7100 for on-call service.

Points of Interest: Manassas National Battlefield Park, Manassas Museum.

Website: www.manassasegionalairport.aero

Weather Data Sources: AWOS-3 125.175 (703) 361-6160.

Communications: CTAF 133.1, ATIS 125.175 (704) 361-6160, Potomac APP/DEP CON 124.65, Tower 133.1 (1130-0330Z±), GND CON 121.8, CLNC DEL 120.2 (when twr clsd POTOMAC CLNC DEL 120.2),

Navigation Aids: ARMEL (L) VORTAC 113.5, TILLE NDB (LOM) 346

Published Instrument Approach: Yes

Approach Lighting: Rwy 16L MALSR, REIL, PAPI; Rwy 34R REIL, PAPI; Rwy 16R REIL, PAPI; Rwy 34L REIL, PAPI

MANASSAS

Latitude N38°43.29'
Longitude W77°30.93'

Field Elevation
192