

TANGIER ISLAND (TGI)

4 W



Sectional Chart: Washington
Runway: Rwy 02-20 H2426 x 75 (ASPH); Rwy 20 thld dsplcd 183'
Traffic Pattern: TPA 605 (600) light acft, 1505 (1500) heavy acft; Rwy 02 Right traffic
Runway Lights: None
Rotating Beacon: OTS indefinitely
Fuel: None
Maintenance: None
Manager: Renee Tyler; P.O. Box 244, Tangier, Virginia 23440; (757) 891-2438
Airport Telephone: (757) 891-2496
Airport Operators: Town of Tangier; P.O. Box 244, Tangier, Virginia 23440; (757) 891-2438
Hours of Operation: Attended Apr-Oct Sat-Sun 1300-2130Z±. ARPT CLOSED SS-SR daily.
Remarks: Be alert Restricted Area 1 mile west of arpt, hi-speed acft drop bombs and fire live ammunition in area. PAEW adjacent to all rwys, twys, and ramps. Ldg/Parking fee to help pay for rwy rehabilitation.

Points of Interest: Historic Tangier Island, Famous Chesapeake House (restaurant), Waterfront Restaurant, Fisherman's Corner Restaurant, Lorraine's Restaurant, Gift shops, Bike Rental, Golf Cart Rental, Fishing, Hunting, Tangier History Museum
Web Site: www.tangierisland-va.com
Weather Data Sources: None
Communications: CTAF/UNICOM 122.8; Cape Charles RCO 122.1R 112.2T (Leesburg Radio); Patuxent APP/DEP CON 121.0 (Mon-Fri 0400-1200Z±, Sat-Sun 1300-2300Z±, clsd holidays); Washington Center APP/DEP CON 133.9 (Mon-Fri 0400-1200Z±, Sat-Sun 2300-1300Z±)
Navigation Aids: Cape Charles (L) VORTAC 112.2
Published Instrument Approach: Yes
Approach Lighting: None

TANGIER

Latitude N37°49.51'
Longitude W75°59.87'

Field Elevation
5