

DANVILLE REGIONAL (DAN)

3 E



Sectional Chart: Cincinnati

Runway: Rwy 02-20 H6500 x 150 (ASPH-GRVD), Rwy 20 thld dsplcd 900'; Rwy 13-31 H4020 x 100 (ASPH)

Traffic Pattern: Left; TPA-1371 (800) lgt aircraft, 2071 (1500) turbine aircraft.

Runway Lights: Rwy 02-20 HIRL; Rwy 13-31 MIRL

Rotating Beacon: Yes

Fuel: 100LL, Jet A

Maintenance: Major AF & PP

Manager: Marc Adelman, (434) 799-5110

Airport Telephone: (434) 799-5110

Airport Operators: General Aviation, 424 Airport Drive, Danville, Virginia 24540, (434) 793-7033

Hours of Operation: Attended Mon.-Fri. 1100-0200Z±. Sat.-Sun. 1200-0000Z±. Arpt. unattended Christmas Day.

Remarks: Rwy 02-20 cracks in pavement. Birds and deer on and in/ovf arpt. Trees penetrating 7:1 transitional sfc of Rwy 31 both sides, first 1000'. Ctc arpt administration prior to conducting specialized aero activities (434) 799-5110. Rwy 02 is designated calm wind rwy. Rwy 31 VASI OTS indefinitely. ACTIVATE

HIRL Rwy 02-20; MIRL Rwy 13-31; REIL Rws 13 and 31 and 20; MALSR Rwy 02; VASI Rws 13 and 31; PAPI Rws 02 and 20 – CTAF.

Points of Interest: Goodyear, Wreck of Old '97, Danville Science Center, Brockway Glass, Last Confederate Capitol, Millionaire's Row, World's Best Tobacco Market, Averett University, Nestles Company, near Smith Mountain, Hargrave Military Academy, Chatham Hall, Golf Courses, Shopping Malls, Bed and Boarding Houses, Virginia International Raceway.

Web Site: www.danville-va.gov/index.aspx?nid=507

Weather Data Sources: ASOS 128.125, (434) 799-1701

Communications: CTAF/UNICOM 123.05; RCO 122.2 (Leesburg Radio), Washington Center APP/DEP CON 124.05

Navigation Aids: South Boston (L) VORTAC 110.4, (L) VOR 113.1, ILS 110.7

Published Instrument Approach: Yes

Approach Lighting: Rwy 02 MALSR, PAPI; Rwy 20 REIL, PAPI; Rwy 13 REIL, VASI; Rwy 31 REIL, VASI

DANVILLE

Latitude **N36°34.37'**
Longitude **W79°20.17'**

Field Elevation
571