



Sectional Chart: Washington
Runway: Rwy 05-23 H2300 x 40 (ASPH); Rwy 23 thld 23 dsplcd 440'.
Traffic Pattern: Left
Runway Lights: MIRL
Rotating Beacon: Yes
Fuel: 100LL
Maintenance: Limited AF & PP
Manager: Brent Hall, P.O. Box 518, Gordonsville, VA 22942-0518, (434) 996-5911
Airport Telephone: None
Airport Operators: Brent Hall, P.O. Box 518, Gordonsville, VA 22942-0518, (434) 996-5911 or (434) 989-5542.
Hours of Operation: Unattended.
Remarks: Rwy 05-23 old crackseal six inches wide in places, very soft. ACTIVATE MIRL Rwy 05-23 CTAF.
Points of Interest: Historic Gordonsville, Barboursville, Horton Vineyards, James Madison's

"Montpelier", Lake Anna.
Website: www.townofgordonsville.org/index.aspx?nid=125
Weather Data Sources: Hazardous Inflight Weather Advisory Service (HIWAS) 115.6 GVE.
Communications: CTAF/UNICOM 123.0, RCO 122.1R 115.6T (Leesburg Radio), Potomac APP/DEP CON 132.85.
Navigation Aids: GVE VOR 115.6
Published Instrument Approach: None
Approach Lighting: Rwy 05-23 APAP

GORDONSVILLE	Latitude N38°09.36' Longitude W78°09.95'	Field Elevation 454
---------------------	---------------------------------------------	------------------------