

HUMMEL FIELD (W75)

6 E



Sectional Chart: Washington

Runway: Rwy 01-19 H2270 x 45 (ASPH); Rwy 01 thld dsplcd 135'

Traffic Pattern: Left

Runway Lights: MIRL

Rotating Beacon: Yes

Fuel: 100 LL

Maintenance: None

Manager: Charles M. Culley, Jr. (County Administrator); P.O. Box 428, Saluda, Virginia 23149-0428; (804) 758-4330

Airport Telephone: (804) 758-0538

Airport Operators: Middlesex County; 877 General Puller Hwy., Saluda, Virginia 23149; (804) 758-4330

Hours of Operation: Attended 1300-2100Z±

Remarks: Unattended Thanksgiving and Christmas Day. Drainage swales full length of rwy on both sides. Use of exit in front of Hummel Aviation advised. Birds and deer on and in vof arpt during winter. Departing Rwy 01-19 climb to

500 ft before any turn out; arriving acft use wide pattern to avoid populated areas E and W of arpt. ACTIVATE MIRL Rwy 01-19 – CTAF.

Points of Interest: Tides Inn, Pilot House Restaurant (walk or taxi to restaurant), Eckhard's Restaurant, Windmill Point Marina, Regent Point Marina, Town of Urbanna (Home of the Oyster Festival), Rappahannock River, Historic Christ Church

Web Site: www.co.middlesex.va.us/hummel.htm

Weather Data Sources: None

Communications: CTAF/UNICOM 123.0, Norfolk APP/DEP CON 126.05

Navigation Aids: Harcum (L) VORTAC 108.8

Published Instrument Approach: Yes

Approach Lighting: Rwy 01-19 APAP

SALUDA

Latitude N37°36.15'
Longitude W76°26.80'

Field Elevation
30